



Electric shock can cause:

- muscle spasms
- weakness
- shallow breathing
- rapid pulse
- severe burns
- unconsciousness
- death.

In a shock incident, the path that electric current takes through the body gets very hot. Burns occur all along that path, including the places on the skin where the current enters and leaves the body.